

Imray Correction Notice

01 September 2011

Chart 2200+2 WGS 84

Edition Dec 2007

Date of printing Dec 2007

The following corrections should be noted:

1 Lymington River (Plan A)

Insert Lt Fl.R.2s at R bn in 50°45'·29N 1°31'·69W (ILNW 59/08)

2 Christchurch Bay, Milford southwestwards

Delete circle and lgd *Scientific Instruments* in 50°43'·19N 1°37'·01W (ILNW 234/08)

3 Christchurch (Plan B)

Substitute G bn with triangular topmk for R bn with rectangular topmk in 50°43'·47N 1°44'·55W (ILNW 389/08)

4 Christchurch Harbour, Mudeford Quay (Plan B)

Amend Lt 2F.G.(vert) to Fl.G.2s in 50°43'·54N 1°44'·34W (ILNW 86/09)

5 Christchurch Bay

Move Y spher Lt buoy Fl(5)Y.20s in 50°42'·48N 1°35'·18W to 50°42'·75N 1°36'·91W. (ILNW 459/09)

6 Approaches to Lymington (Plan A)

Move Lt bns:

Seymour's Post Fl.R.2s to 50°44'·89N 1°31'·16W

Bag of Halfpence to 50°44'·95N 1°31'·15W and add Lt Fl.R.2s

Enticott Fl.G.2s to 50°44'·97N 1°31'·08W

Cocked Hat Fl.R.2s to 50°45'·06N 1°31'·17W

Insert:

G starboard Lt bn **No3A** Fl.G.2s in 50°44'·54N 1°30'·73W

BW bn in 50°44'·83N 1°31'·20W (old **Seymour's Post** position)

R can Lt buoy **No8A** Fl.R.2s in 50°44'·80N 1°31'·16W

R port Lt bn **No10** Fl.R.2s in 50°45'·03N 1°31'·14W

Substitute R port Lt bn **No8** Fl.R.2s for R can Lt buoy Fl.R.2s in 50°44'·72N 1°31'·06W

Insert Lt Fl.R.2s at R port bn **Harper's Post S** in 50°45'·11N 1°31'·36W

Delete E card Lt bn **Harper's Post Q(3)**10s in 50°45'·12N 1°31'·47W (ILNW 204/10)

7 Approaches to Lymington (Plan A) (Further information - see ILNW 481/10)

Mariners should be aware that harbour works are now underway in an area to the west of the Cocked Hat R port Lt bn. These works are expected to continue until September 2010.

For further details, contact the Lymington Harbourmaster. (ILNW 205/10)

8 Approaches to Lymington (Plan A)

Mariners are advised that the new breakwater southwest of Cocked Hat bn has been completed.

Full details will be included on the next edition of this chart. In the meantime, please consult with the Lymington Harbour Commissioners for further information. (ILNW 481/10)

9 Approaches to Needles Channel

Substitute Whis for Bell at **Fairway** safe water Lt buoy in 50°38'·23N 1°38'·98W (ILNW 1/11)

10 Needles Channel

Move **SW Shingles** Fl.R.2·5s Lt buoy to 50°39'·29N 1°37'·52W (ILNW 2/11)

11 Dolphin Bank southwestwards

Insert Y pillar Lt buoy Fl.Y.3s in 50°38'·47N 1°40'·46W (ILNW 302/11)

