

Imray Correction Notice

16 June 2011

Chart D23 WGS 84

Edition Jun 2007

Date of printing Jun 2007

The following corrections should be noted:

1 **Aruba, St Nicholaas**

Amend Lt Fl.R.3s23ft7M to Fl.R.4s23ft7M in 12°25'·85N 69°55'·10W. (ILNW 63/10)

2 **General Notice**

Before visiting this area, mariners are advised to check www.safetyandsecuritynet.com.

The Venezuelan HO changes light characteristics on a regular basis, making it difficult to keep corrections up to date. Lights are seldom moved, but characteristics are regularly changed. (ILNW 138/10)

3 **Aruba**

Amend Lt Q.G to Fl.G in 12°24'·90N 69°53'·78W (ILNW 184/10)

4 **Aruba, Haven Barcadera**

Amend Lt descrip. Ldg F.Y to Ldg F.G at Lt in 12°28'·85N 69°59'·85W (ILNW 137/11)